


Winkel	Bohrabstand 1
α	$34,5 + 20/\tan(\alpha)$
75°	39,9
70°	41,8
65°	43,8
60°	46,0
55°	48,5
50°	51,3
45°	54,5

Winkel	Bohrabstand 2
α	$34,5 + 13/\tan(\alpha)$
75°	38,0
70°	39,2
65°	40,6
60°	42,0
55°	43,6
50°	45,4
45°	47,5



Schraube-Anziehmoment	M8x1,25 (8.8)	25,0 Nm	Schraube-Anziehmoment	M5x0,8 (8.8)	5,9 Nm
Schraube-Anziehmoment	M6x1,00 (8.8)	10,0 Nm	Schraube-Anziehmoment	M4x0,70 (8.8)	3,0 Nm

